

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

Crawford Guard Station, Barn (Bldg 2172)
Boise National Forest
Cascade Vicinity
Valley County
Idaho

HABS No. ID-53

HABS
ID,
43-CASC.V,
2A -

J. Ceronie and Marie Neubauer, Photographers June 1984

- ID-53-1 3/4 VIEW LOOKING NORTHEAST
- ID-53-2 SOUTH SIDE
- ID-53-3 EAST BACK
- ID-53-4 NORTH SIDE
- ID-53-5 INTERIOR VIEW LOOKING NORTH
- ID-53-6 INTERIOR VIEW LOOKING SOUTH
- ID-53-7 INTERIOR VIEW OF ORIGINAL BARN LOOKING NORTH
- ID-53-8 DETAIL OF TRUSS SYSTEM LOOKING EASTNORTHEAST
- ID-53-9 CLOSEUP OF ANIMAL STALL AND FEEDING TROUGH IN BACKGROUND LOOKING EAST
- ID-53-10 DETAIL OF TRUSS SYSTEM LOOKING NORTH
- ID-53-11 DETAIL OF POST FOUNDATION STONE INTERIOR WALL LOOKING SOUTH